

You can obtain only six 21 ohm resistors from the stock room. How can you achieve a resistance of 14 ohms?

done

Nov 7-5:45 PM

You can obtain only six 21 ohm resistors from the stock room. How can you achieve a resistance of 14 ohms?

Nov 2-10:26 AM